





6"x6" non-slip tile never installed, employees slipping













Bakery cove tile needs replacement and mold abated

